UNITED STATES DEPARTMENT OF COMMERCE Patent and Trademark Office ASSISTANT SECRETARY OF COMMERCE AND COMMISSIONER OF PATENTS AND TRADEMARKS P.O. Box 1450

Alexandria, VA 22313-1450

September 26, 2006

Christopher F. Regan, Allen, Dyer, Doppelt, Milbrath, Gilchrist, P.A. P.O. Box 3791

Orlando FL 32802-3791

Patent No. : 6,891,188 B2

Inventor(s) : Robert J. Mears, et al.

Issued

: May 10, 2005

For

SEMICONDUCTOR DEVICE

INCLUDING BAND-ENGINEERED

SUPERLATTICE

Doc. No. 62601_CON3

To Whom It May Concern:

The Certificate of Correction issued on <u>September 26, 2006</u>, issued in error, in that error(s) was made in identifying the patent number and/or keying text/corrections, i.e.:

The issue date in the heading of cofc has been incorrectly entered in the heading of the issued cofc. A superseding cofc will be issued to correct the patent issue date to read --May 10, 2005--.

Therefore, a certificate of correction will be issued to correct (supersede) the Certificate of Correction containing error(s), made during preparation of the Certificate of Correction, as noted above.

No further response is required, from applicants (attorney). However, errors discovered by attorney, other than as noted and described above, should be noted on *a copy* of the Certificate of Correction that was issued in error, accompanied by a signed transmittal letter and submitted directed to this Branch.

Antonio Johnson (703) 308-9390 ext. 111 For Cecelia Newman, Supervisor Decisions & Certificates of Correction Branch (703) 305-8309 / 703-308-9390 ext. 102 cbn